ADM SITE PHOTOS

Site photo report

Anonymised sample

Drainage and site operations

Three real work photographs with concise notes, prepared using our app's report layout.

3	3	3	PDF
Work photographs	Site notes	Report pages	High-resolution copy

ABOUT THIS SAMPLE

Selected work examples show how photographs and notes can be presented to a client. Notes were prepared for this sample from the photographs and confirmed work details.

The two drainage photographs show the same work. The tracked dumper is a separate example. These images are not presented as a before-and-after sequence or a complete project record.

Job and client names, dates, exact locations and GPS details are withheld. No measurements, inspection approvals or completed results are implied.

Anonymised sample / Drainage

Drainage installation

Photo 001 of 3



CAPTURED - LOCAL DEVICE TIME

Withheld for sample

CAPTURED - UTC

Withheld for sample

LOCATION

Withheld for sample

GPS FIX / REPORTED ACCURACY

Withheld for sample

PHOTO REFERENCE

Sample 001

Site note - prepared for this sample

Remedial drainage alongside an existing installation. Outlet levels and available fall determine the route and where a run can break away.

Below-ground drainage detail

Photo 002 of 3



CAPTURED - LOCAL DEVICE TIME

Withheld for sample

CAPTURED - UTC

Withheld for sample

LOCATION

Withheld for sample

GPS FIX / REPORTED ACCURACY

Withheld for sample

PHOTO REFERENCE

Sample 002

Site note - prepared for this sample

Stone-filled drainage run shown before backfilling. The close view records below-ground detail that will be concealed when the trench is filled.

Anonymised sample / Site operations

Site access and material handling

Photo 003 of 3



CAPTURED - LOCAL DEVICE TIME

Withheld for sample

CAPTURED - UTC

Withheld for sample

LOCATION

Withheld for sample

GPS FIX / REPORTED ACCURACY

Withheld for sample

PHOTO REFERENCE

Sample 003

Site note - prepared for this sample

Tracked dumper at the working area. The photograph records the surrounding ground and working access for material handling.

PHOTOGRAPHS WITH CONTEXT

A useful site record pairs a wider view of the work with closer detail and a short note. Job-specific photographs, dates and available GPS information can be included in the client report.

The identifying fields above are deliberately withheld for this website sample. Reporting requirements can be agreed as part of the work.